

Report no.
24-14253-02nd-05

Project no.
5242178

Report date:
May 29, 2024

Office:
Shanghai

REPORT OF ACTIVITY

General scope of activity: Third Party Inspection	Dates of all related activity: May 28, 2024
Client: Company name: Dongtai Martian Ship Equipment Co., Ltd. Address: No.130, Group 4, Tuanjie Village, Fu'an Town, Dongtai City, Jiangsu Province, P.R. China Contact(s): Mr. Zhang Zhen Hua PO/shop/contract or job no: --	Supplier: Company name: Dongtai Martian Ship Equipment Co., Ltd. Address: No.130, Group 4, Tuanjie Village, Fu'an Town, Dongtai City, Jiangsu Province, P.R. China Contact(s): Mr. Zhang Zhen Hua PO/shop/contract or job no: --
Subvendor - 1: N/A Company name: -- Address: -- Contact(s): -- PO/shop/contract or job no: --	Subvendor - 2: N/A Company name: -- Address: -- Contact(s): -- PO/shop/contract or job no: --
Component description(s): 1. Fall Preventer Device Type: HXFPD-6T Φ20mm x 1m (Quantity: 100 pcs)	Results: Meets requirements <input checked="" type="checkbox"/> Subject to condition(s) noted <input type="checkbox"/> Does not meet requirements <input type="checkbox"/>

This is to certify that the undersigned did at the request of **Dongtai Martian Ship Ship Equipment Co., Ltd.** attend the **Dongtai Martian Ship Ship Equipment Co., Ltd.** located at **No.130, Group 4, Tuanjie Village, Fu'an Town, Dongtai City, Jiangsu Province, P.R. China** on **May 28, 2024** in order to carry out the scope of services described below:

1.0 Scope of service activity:

The scope of activity included the following:

- .1 Document review
- .2 Witness safe working load test
- .3 Issue this Report of Activity

2.0 Details:

- .1 Applicable technical specification and relevant standards.
 - a. Supplier's test procedure (No.: HXFPD002 Rev: 003).
- .2 Calibration certificates of applied inspection instruments were reviewed, and the expired dates were within the validity. See the table below:

Inspection Instrument	Serial No.:	Calibration Certificate No.:	Valid Date
Electronic hoist scale Type: OCS-B10	/	ZZ20240222Z0012	February 21, 2025

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and the liability of ABS Consulting Inc. (hereinafter referred to as ABS Consulting) shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall ABS Consulting be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only upon those items actually inspected by ABS Consulting and which are covered by this Report.

This certificate/ report is issued by ABS Consulting, and shall not be construed as a partial or complete fulfilment of requirement(s) specified in ABS Classification Rules/ Guides/ Notations

Form IS-2

Reporting, TIV-PRO-00025

Attachment B, TIV-ATT-00206 – Rev. 2

Report no. 24-14253-02 nd -05	Project no. 5242178	Report date: May 29, 2024	Office: Shanghai
--	-------------------------------	-------------------------------------	----------------------------

- .3 According to the supplier's test procedures requirements, there are a total of 100 fall preventer devices in this batch, the undersigned randomly selects products at 5% of the total quantity for safety working load test. After the safe working load test, the visual inspection for the 5 products were performed and no deformed was found, the results were found to be satisfactory. The detailed data are shown in the table below:

Safe Working Load Test				
Number of the product being selected	Required Minimum Safe Working Test Load	Actual Safe Working Test Load	Duration Time	Test Results
24101	6000 kg	6200 kg	5 Minutes	Satisfactory
24131	6000 kg	6180 kg	5 Minutes	Satisfactory
24151	6000 kg	6005 kg	5 Minutes	Satisfactory
24171	6000 kg	6410 kg	5 Minutes	Satisfactory
24191	6000 kg	6355 kg	5 Minutes	Satisfactory

3.0 Identification of item(s) verified:

- .1 The serial number of this batch of fall preventer device is shown in table below:

Product Name	Type	S. W. L	Product Serial Number	Quantity
Fall Preventer Device	HXFPD-6T Φ 20mm x 1m	6000 kg (6T)	24101 thru 24200	100 pcs

- .2 The nameplate of each fall preventer devices was marked with ABS Consulting service stamp "wTs".

4.0 Conclusion:

- .1 Inspections of the **Fall Preventer Device** were carried out within the defined scope of inspection where indicated herein, and the result found satisfactory to the requirement as described in clause 2.1.

5.0 Attachments:

- .1 Digital Photos 4 pieces.

Report prepared and submitted without prejudice.



Kong Xiao Fei
Technical Representative / ABS Consulting

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and the liability of ABS Consulting Inc. (hereinafter referred to as ABS Consulting) shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall ABS Consulting be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only upon those items actually inspected by ABS Consulting and which are covered by this Report.

This certificate/ report is issued by ABS Consulting, and shall not be construed as a partial or complete fulfilment of requirement(s) specified in ABS Classification Rules/ Guides/ Notations

Form IS-2

Reporting, TIV-PRO-00025

Attachment B, TIV-ATT-00206 – Rev. 2

Report no.
24-14253-02nd-05

Project no.
5242178

Report date:
May 29, 2024

Office:
Shanghai

Photos:



Photo #01: Witnessed safe working load test



Photo #02: Witnessed safe working load test



Photo #03: Each nameplate was marked with ABS Consulting service stamps "wTs"



Photo #04: Each nameplate was marked with ABS Consulting service stamps "wTs"

End

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and the liability of ABS Consulting Inc. (hereinafter referred to as ABS Consulting) shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall ABS Consulting be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only upon those items actually inspected by ABS Consulting and which are covered by this Report.

This certificate/ report is issued by ABS Consulting, and shall not be construed as a partial or complete fulfilment of requirement(s) specified in ABS Classification Rules/ Guides/ Notations

Form IS-2

Reporting, TIV-PRO-00025

Attachment B, TIV-ATT-00206 – Rev. 2